




Staple hardware cloth (any size will work, the more rigid the better) onto frame and cover with window screening.



If you are making your own box, add handles; make sure they will clear your outer cover.

Fill with 4"-6" of wood chips - DO NOT USE SAWDUST!! Using cedar might help with mite control.



Cut openings in front and sides for air flow, 3/4" x approx 2" and cover with 1/4" to 1/2" hardware cloth to keep mice out.

No inner cover is used; this replaces it.